

2)	Road up to the roundabout with Manchester Road in the last 5 years, total number of defects that have been reported to the	A2 – 15
2)	· ·	A2 – 15
	Council on that stretch of highway,	
3)	total amount in compensation that the Council paid out in relation to the poor road surface on that stretch of highway,	A3 - None
4)	estimated cost of fully resurfacing the above stretch of highway,	A4 - £60k
5)	the estimated date when the full resurfacing of that stretch of highway is going to take place,	A5 - There is no current date for resurfacing this section of highway. All highway planned maintenance schemes are listed on the council's website www.wigan.gov.uk/highwaymaintenance
	5)	5) the estimated date when the full resurfacing of that