

Request

Request for walked reports:-

Gloucester Street, Atherton
Manchester Road, Ince
Springfield Road, Atherton
Swan Lane, Hindley
Warrington Road, Ince
Wigan Road, Atherton

Response

Please see attached latest walked inspections for the streets requested.

Highways Inspection Report

Street: Gloucester Street Town: Atherton

Limits: Wigan Road To: Greendale

Inspection Date: 18/01/2024 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		
Notes:					

Highways Inspection Report

Street: Manchester Road Town: Ince

Limits: Darlington Street East To: Wigan Road

Inspection Date: 10/01/2024 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Junction of Hmphrey Street	Enforcement	Highway Obstructions	Streetwork Enforcement		00539503
Opposite Lighting Column 37	Enforcement	Highway Obstructions	Streetwork Enforcement		00539504
Junction of Makerfield Way on crossing	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC	40mm - 44mm	00539505
Opposite Lighting Column 46	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC Traffic management meeting required requiring detailed assessment from Traffic Officer	50mm or Above	00539506
Near Lighting Column 47	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC	40mm - 44mm	00539507
Between Lighting Columns 27. 28	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC	40mm - 44mm	00539508
Fronting Lighting Column 21 at gully	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC Traffic management meeting required requiring detailed assessment from Traffic Officer	40mm - 44mm	00539509
Opposite Lighting Column 7	Footway Non Principal	Bitmac	Bitmac Depression GMRAPS Permit Required	30mm - 34mm	00539572
Fronting Lighting Column 7	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC GMRAPS Permit Required	40mm - 44mm	00539573
Junction of Ince Hall Ave	Enforcement	Highway Obstructions	Streetwork Enforcement		00539574
Junction of Anderton Street	Defective Apparatus-Transco	Service Box - Small	Uneven Box		00539575
Junction of Keble Street	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC	25mm - 29mm	00539576
Junction of Keble Street	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC	25mm - 29mm	00539577
Near Junction Kirkless St	Enforcement	Highway Obstructions	Streetwork Enforcement		00539580

Notes:

539384 in date.

Highways Inspection Report

Street: Springfield Road Town: Atherton

Limits: Hillside Avenue To: Upton Road

Inspection Date: 12/03/2024 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At Junction Upton Road	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC GMRAPS Permit Required	40mm - 44mm	00542564
Junction of Upton Road	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC GMRAPS Permit Required Traffic management meeting required requiring detailed assessment from Traffic Officer	40mm - 44mm	00542563
Notes:					

Highways Inspection Report

Street: Swan Lane Town: HINDLEY GREEN

Limits: Atherton rd To: Borough Bounday

Inspection Date: 02/12/2023 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Between alder lane and green lane	Defect Risk Assessment	Defect Risk Assessment	Carry out Defect Risk Assessment		00538182

Notes:

Highways Inspection Report

Street: Warrington Road Town: Ince

Limits: Ince Green Lane To: Moss Lane

Inspection Date: 06/12/2023 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Side of Lighting Column 38	Footway Non Principal	Bitmac	Bitmac Deterioration GMRAPS Permit Required	25mm	00538333
Between Lighting Columns 33 and. 34	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC GMRAPS Permit Required	30mm - 34mm	00538334
Between Lighting Columns 38 and 39	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC	40mm - 44mm	00538335
Outside House Number 563	Footway Non Principal	Bitmac	Bitmac Deterioration	25mm - 29mm	00538336
Outside House Number 563	Footway Principal	Flags	Damaged Tactile Flag GMRAPS Permit Required	Below 20mm	00538337

Notes:

Include 25m from Roundabout Chatsworth Fold junction

Highways Inspection Report

Street: Wigan Road Town: Atherton

Limits: Gloucester Street To: Smallbrook Bridge

Inspection Date: 18/01/2024 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Side of House Number 352a	Footway Non Principal	Bitmac	Bitmac Deterioration GMRAPS Permit Required	20mm - 24mm	00539921
Outside House Number 534	Footway Non Principal	Bitmac	Bitmac Deterioration GMRAPS Permit Required		00539922
At House Number 213	DLO Notification	Repairs	Work Below Standard Reportable Defect		00539919
Near Junction Roundabout The Talbot	Carriageway Non Principal	Bitmac	Pothole GMRAPS Permit Required	50mm or Above	00539923

Notes: