

Request:

The road surface from 246 swan lane to number 40 swan lane Hindley green, is eroding very fast.

Please can i have the most FOI walked report on this stretch.

Response:

Please see below latest walked inspection for Swan Lane. The latest inspection was undertaken on the 12/06/2023.



Highways Inspection Report

Street: Swan Lane Town: HINDLEY GREEN

Limits: Atherton Rd To: Borough Bounday

Inspection Date: 12/06/2023 Inspected By:

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Junction of coupland road	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC GMRAPS Permit Required		00531071
Junction of coupland road	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC GMRAPS Permit Required		00531072
Notes:					