



Our ref: BTP83524 Location: Haigh Road, Aspull, Wigan, WN2 1RN. I am instructed on behalf of British Telecommunications PLC. To assist me with my investigations, and in accordance with the Freedom of Information Act 2000, I require -

Copies of the highway inspection records together with all opening/closing notices, defect notices and records of complaints for 2 years prior to 16/03/2023.

Please also provide a copy of the first highway inspection record after 16/03/2023 relating to the location.

[Please see attached documentation as requested:](#)

- [Highway Inspections](#)
- [Highway Enquiries](#)
- [Highway Opening Notices](#)

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 31/03/2021 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 28/04/2021 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		
Notes:					

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Rd To: Holly Rd

Inspection Date: 07/05/2021 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

**Handheld device not working for this inspection.
Ad hoc ticket issued;
496067
496068
496072**

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 28/05/2021 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

No reportable defects

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 28/06/2021 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Entrance to Co op	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC	40mm - 44mm	00499938

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Rd To: Holly Rd

Inspection Date: 02/08/2021 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes: **Adhoc inspection complete due to mayrise mapping issues, reportable defects identified on job 502028 and 502029**

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 29/07/2021 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Holly Rd To: Haigh Rd Haigh

Inspection Date: 11/08/2021 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At Lighting Column 11	Reactive Gully Clean	Reactive Gully Clean	Clean blocked gully		
At Lighting Column 10	Reactive Gully Clean	Reactive Gully Clean	Clean blocked gully		
Opposite Lighting Column 11	Reactive Gully Clean	Reactive Gully Clean	Clean blocked gully		
Opposite House Number 99	Footway Non Principal	Kerbs	Damaged Straight Kerb Bitmac Footway	50mm or Above	00502503

Notes:



Wigan Council
Places Directorate
Wigan Life Centre
College Avenue
Wigan
WN1 1NJ

Inspection Schedule: 014380

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: Inspected By:

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

--

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 07/09/2021 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Outside Shop COOP	DLO Notification	Repairs	Incomplete Drainage Work		00503932

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 27/09/2021 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

No reportable defects

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 29/10/2021 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Rd To: Holly Rd

Inspection Date: 05/11/2021 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

**Handheld device not working for this inspection.
Ad hoc ticket issued;
507501
507502
507503
507504**

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 29/11/2021 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

No Reportable Defects

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 23/12/2021 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At street	No Reportable Defects	uneven	No Reportable Defects		

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 27/01/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

No reportable defects

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Rd To: Holly Rd

Inspection Date: 07/02/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Notes: Handheld device not working for this inspection. Ad hoc ticket issued; 511383 511384					

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Holly Rd To: Haigh Rd Haigh

Inspection Date: 08/02/2022 Inspected By: ██████████

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes: **Handheld device not working for this inspection.**
Ad hoc ticket issued;
511492
511493

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: Inspected By:

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 22/02/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 31/03/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 12/04/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Rd To: Holly Rd

Inspection Date: 10/05/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

no reportable defects

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 19/05/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Rd To: Holly Rd

Inspection Date: Inspected By:

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: Inspected By:

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 21/06/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Outside House Number 125	Enforcement	Highway Obstructions	Streetwork Enforcement		00516928
Notes:					

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Rd To: Holly Rd

Inspection Date: 07/07/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes: **inspected no geometry**

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 13/07/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

No Reportable Defects.

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Rd To: Holly Rd

Inspection Date: 01/08/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Holly Rd To: Haigh Rd Haigh

Inspection Date: 12/08/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 23/08/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

No Reportable Defects.

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 16/09/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 09/10/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:



Wigan Council
Places Directorate
Wigan Life Centre
College Avenue
Wigan
WN1 1NJ

Inspection Schedule: 015507

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Rd To: Holly Rd

Inspection Date: 07/11/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 10/11/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 15/12/2022 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Opposite Holly Nook	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC GMRAPS Permit Required	40mm - 44mm	00523924
Notes:					

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 12/01/2023 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:



Wigan Council
Places Directorate
Wigan Life Centre
College Avenue
Wigan
WN1 1NJ

Inspection Schedule: 015727

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Rd To: Holly Rd

Inspection Date: 03/02/2023 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 09/02/2023 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Holly Rd To: Haigh Rd Haigh

Inspection Date: 17/02/2023 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 15/03/2023 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		
Notes:					

Highways Inspection Report

Street: Haigh Road Town: Aspull

Limits: Wigan Road To: Haigh Rd Haigh

Inspection Date: 19/04/2023 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Near Lighting Column 4	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC GMRAPS Permit Required Traffic management required requiring stop/go boards	40mm - 44mm	00528896
Near Lighting Column 4	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC GMRAPS Permit Required Traffic management required requiring stop/go boards	40mm - 44mm	00528895
Junction of Crawford avenue	Carriageway Non Principal	Bitmac	DETERIORATION BITMAC GMRAPS Permit Required Traffic management required requiring stop/go boards	40mm - 44mm	00528894
Notes:					

Wigan MBC
Third Party Reports

21-April-2023

Defect ID	483116
Street	Haigh Road Aspull Central Aspull
Location	Entrance to Co op
Reported	04/03/2022 9:38
Defect	Pothole
Details	A number of potholes are present on the pavements and road as you drive right into the car park at the Coop on Haigh Road. It is quite a nuisance when turning into the car park Extra information supplied by the user Can you confirm that the location plotted on the map is the location of the issue? : Yes Please provide a telephone number so that we can contact you to discuss your enquiry further if required. : 07758613338 Is the defect located on the council's adopted highway? : Yes First name, Last name : <input type="text"/>
Inspected	05/04/2022 11:02
Item	Agilisys Digital
Sub Item	Highway Service
Defect	Pothole
Job No	

Defect ID	483858
Street	Haigh Road Aspull Central Aspull
Location	Entrance to Co op
Reported	12/03/2022 12:09
Defect	Pothole
Details	On the footpath at Aspull co-op going into the car park there are very big potholes and your car struggles to get off the car park. Extra information supplied by the user Can you confirm that the location plotted on the map is the location of the issue? : Yes Please provide a telephone number so that we can contact you to discuss your enquiry further if required. : 01942747526 Is the defect located on the council's adopted highway? : Yes First name, Last name : <input type="text"/>
Inspected	05/04/2022 11:03
Item	Agilisys Digital
Sub Item	Highway Service
Defect	Pothole
Job No	

Defect ID	486603
Street	Haigh Road Aspull Central Aspull
Location	
Reported	25/04/2022 15:57
Defect	Highway Obstructions
Details	99 Haigh Road, Aspull, WN2 1RP Speed limit post has been knocked down (probably by other vehicle) and is on pavement Extra information supplied by the user Can you confirm that the location plotted on the map is the location of the issue? : Yes Please provide a telephone number so that we can contact you to discuss your enquiry further if required. : 07980945515 Is the defect located on the council's adopted highway? : Yes
Inspected	13/05/2022 9:00
Item	Agilisys Digital
Sub Item	Highway Service
Defect	Highway Obstructions
Job No	

Defect ID	487647
Street Location	Haigh Road Aspull Central Aspull
Reported	10/05/2022 14:26
Defect Details	<p>Highway Obstructions</p> <p>Message from a Facebook user who does not have the ability to report Can someone please report the road sign ?? on the junction of St David's crescent and Haigh Road Aspull, it's a danger to pedestrians ????? and drivers. Thanks</p> <p>Extra information supplied by the user Can you confirm that the location plotted on the map is the location of the issue? : Yes Please provide a telephone number so that we can contact you to discuss your enquiry further if required. : 01942522388 Is the defect located on the council's adopted highway? : Yes Telephone number of reporter (MANDATORY - if they do not have an email address) : tiffany.dacre@wigan.gov.uk First name, Last name <input type="text"/></p>
Inspected	16/05/2022 9:00
Item	Agilisys Digital
Sub Item	Highway Service
Defect	Highway Obstructions
Job No	

Defect ID	496786
Street Location	Haigh Road Aspull Central Aspull
Reported	21/09/2022 8:28
Defect Details	<p>Highway Obstructions</p> <p>Opposite the field on Haigh Rd, Aspull, a resident is using cones stolen from some work previously carried out by United Utilities on Haigh Rd, to block the pavement in front of their house. This is obstructive to the many mums with buggies walking to the 3 schools in the area twice a day.</p>
Inspected	29/09/2022 11:00
Item	Agilisys Digital
Sub Item	Highway Service
Defect	Highway Obstructions
Job No	

Defect ID	507338
Street Location	Haigh Road Aspull Central Aspull
Reported	13/03/2023 11:38
Defect Details	<p>Pothole</p> <p>Pothole in the middle of the road Additional location details: Haigh road in the middle of the road just outside CO-OP</p>
Inspected	29/03/2023 12:00
Item	Agilisys Digital
Sub Item	Highway Service
Defect	Pothole
Job No	

Defect ID	509827
Street Location	Haigh Road Aspull Central Aspull
Reported	20/04/2023 10:19
Defect Details	Councillor Enquiry Pot holes on Haigh Road, Aspull
	There are three bad potholes/group of potholes on Haigh Road in Aspull:
	1. By the turn into Crawford Avenue
	2. Outside the Co-op and near Our LadyÆs School
	3. By Our LadyÆs Church
	Please could these be assessed and remedied as they are pretty bad.
	Many thanks,
	<input type="text"/>
Inspected Item	Agilisys Digital
Sub Item	Highway Service
Defect	Councillor Enquirv

Defect ID	509869
Street Location	Haigh Road Aspull Central Aspull 101A Haigh Road, Aspull, Wigan WN2 1RP
Reported	20/04/2023 14:28
Defect Details	Pothole large area of potholes in middle of road outside CO_OP store on Haigh Rd ASPULL Additional location details: 101A Haigh Road, Aspull, Wigan WN2 1RP
Inspected Item	Agilisys Digital
Sub Item	Highway Service
Defect	Pothole
Job No	