

### Request:

Can you please provide me the last Road Inspection record, date and details under the freedom of information act for Tatton Drive, Harlech Street, and Clarence Street all in Ashton In Makerfield with regard to any defects that have been identified, their risk and severity etc, and if there is any current plan for any remedial works planned in this area.

### Response:

Please see below records for Tatton Drive, Harlech Street and Clarence Street. The streets are all subject to an annual walked inspection and were last carried out May 2023. Attached reports shows that no reportable defects were identified on any of these streets.

The Council's planned highway maintenance schemes are published on its website and can be viewed by the following link:

https://www.wigan.gov.uk/Resident/Parking-Roads-Travel/Roads/Highwaymaintenance.aspx

# **Highways Inspection Report**

Street: Clarence Street Town: Ashton-in-Makerfield

Limits: Tatton Drive To: Harlech Street

Inspection Date: 24/05/2023 Inspected By:

Location of Defect	Position	M aterial	Nature of Defect	Depth of Defect	Action		
Notes: no geometry ad oc if any defects							

# **Highways Inspection Report**

Street: Harlech Street Town: Ashton-in-Makerfield

Limits: Priory Road To: CDS

Inspection Date: 24/05/2023 Inspected By:

	Location of Defect	Position	M aterial	Nature of Defect	Depth of Defect	Action
Notes: no geometry ad oc if any defects	Notes:	no geome	etry ad oc if	any defects		

# **Highways Inspection Report**

Street: Tatton Drive Town: Ashton-in-Makerfield

Limits: Wentworth Road To: CDS

Inspection Date: 24/05/2023 Inspected By:

Location of Defect	Position	M aterial	Nature of Defect	Depth of Defect	Action		
Notes: no geometry ad oc if any defects							