



**Wigan**<sup>♥</sup>  
**Council**

## **REQUEST 19247**

I require copies of the highway and footway inspection records together with all opening/closing notices, defect notices and records of complaints for 24 months prior to 19 November 2025.

Please also provide a copy of the first highway inspection after 19 November 2025.

The location for our request is Shakerley Road, Tyldesley, Manchester, M29 8FQ

Please also confirm the frequency of the footway inspections.

## **RESPONSE**

Highway and footway inspections attached are walked and driven inspections.

Frequency of inspections are 3 monthly driven inspection and 6 monthly walked inspection.

Opening/closing notice and defects notices are attached.

## Highways Inspection Report

Street: Shakerley Road      Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date: 05/09/2023 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

## Highways Inspection Report

Street: Shakerley Road      Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date:    Inspected By:

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

## Highways Inspection Report

Street: Shakerley Road      Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date: 21/12/2023 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:



Wigan Council  
Places Directorate  
Wigan Life Centre  
College Avenue  
Wigan  
WN1 1NJ

Inspection Schedule: 016637

## Highways Inspection Report

Street: Shakerley Road      Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date:    Inspected By:

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action

Notes:

--

## Highways Inspection Report

Street: Shakerley Road      Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date: 13/02/2024 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Outside House Number 73	Footway Non Principal	Bitmac	Bitmac Deterioration GMRAPS Permit Required	20mm - 24mm	00541060

Notes:

## Highways Inspection Report

Street: Shakerley Road      Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date: 26/03/2024 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

## Highways Inspection Report

Street: Shakerley Road      Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date: 27/06/2024 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

## Highways Inspection Report

Street: Shakerley Road      Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date: 14/08/2024 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Outside House Number 54	Enforcement	Highway Obstructions	Streetwork Enforcement		00549148
Notes:					

## Highways Inspection Report

Street: Shakerley Road      Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date: 04/10/2024 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		
Notes:					

## Highways Inspection Report

Street: Shakerley Road      Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date: 10/01/2025 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

## Highways Inspection Report

Street: Shakerley Road      Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date: 06/02/2025 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Opposite House Number 54	Footway Non Principal	Bollards	Dislodged Non Decorative Bollard GMRAPS Permit Required		00555467
Notes:					

## Highways Inspection Report

Street: Shakerley Road      Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date: 27/03/2025 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

## Highways Inspection Report

Street: Shakerley Road Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date: 27/06/2025 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

## Highways Inspection Report

Street: Shakerley Road      Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date: 06/08/2025 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
Side of Lighting Column 12	Footway Non Principal	Kerbs	Uneven Radius Kerb Bitmac Footway GMRAPS Permit Required	50mm or Above	00561702

Notes:

## Highways Inspection Report

Street: Shakerley Road      Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date: 29/09/2025 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes:

## Highways Inspection Report

Street: Shakerley Road Town: Tyldesley

Limits: Tyldesley Road To: Crawford Avenue

Inspection Date: 06/01/2026 Inspected By: [REDACTED]

Location of Defect	Position	Material	Nature of Defect	Depth of Defect	Action
At full length	No Reportable Defects	uneven	No Reportable Defects		

Notes: